میزان مصرف

النز ۵ متر مربع

ابزار های اجرا

قلم مو غلتک پیستوله

ایرلس



جسبندگی بسیار عالی فام خاص و استاندارد سطحی صاف و صیقلی مقاوم در برابر رطوبت مقاومت در برابر شرایط جوی

تمام فام ها روشن – تيره – الوان

فام رنگ



يوشش عالي

یوشرنگ روغنی نیمه براق آلکیدی



نکات ایــمنــی

جرقه و شعله دورنگه داشته شود.

توصیه می گردد از استنشاق مداوم بخارات

حلال این رنگ در فضاهای بسته خودداری نموده و

حتى الامكان از لوازم ايمني مناسب استفاده و در

صورت تماس با پوست و چشم با آب زیاد شستشو

این رنگ اشتعال زا بوده و بایستی از حرارت،



















دمای ســطح

بسته بــندی

درجه سانتی گراد



ُنوع حلال رنگ

حلال روغني نفت – بنزین



Palaj


میزان براقیت

سطح زیرآیند طبق استاندارد (۴:۱۹۹۲ه۸۸ ISO) باید عاری از هرگونه آلودگی مانند چربی، روغن، گرد و غبار و رطوبت باشد زیرا عوامل باعث کاهش شدید چسبندگی رنگ به سطح می گردد. عمل تمیز کاری باید توسط شوینده های مناسب انجام گیرد. در صورت صاف و صیقلی بودن سطح آستر، به منظور ایجاد چسبندگی بیشتر، سطح می بایست با ابزار مناسب مانند سنباده سایش داده شود. در صورتی که رنگ مستقیما بر روی سطح اعمال شود، نخست باید آماده سازی مربوطه روی سطح مورد نظر انجام گیرد. نواحی آسیب دیده سطح نیز می بایست قبل از اعمال رنگ، مجددا آماده سازی و رنگ آمیزی شود.

آماده سازی سطح

رنگ آلکیدی ، قابلیت استفاده روی همه سطوح، اعم از سطوح گچی، فلزی، چوبی و ... را دارا بوده و از این رنگ، در صنعت ساختمان سازی استفاده های زیادی می شود که در ادامه بصورت جداگانه به کاربرد های این رنگ، اشاره خواهیم کرد. از این رنگ ها، برای حفاظت از انواع سازه ها، در مقابل انواع مختلف عوامل محیطی، از قبیل رطوبت بالا و شرجی زیاد و همچنین جلوگیری از زنگ زدن سازه های فلزی و ... استفاده می شود.

درجه کیفی



نحوه مصرف و اجرا

برای استفاده از پوشرنگ روغنی براق پالاژشیمی، ابتدا سطح مورد نظر را به طور کامل تمیز کرده و از هر نوع آلودگی و چربی پاک کنید. سپس پوشرنگ روغنی براق پالاژشیمی را با استفاده از فرش رنگ، مو، یا رولر رنگ روی سطح مورد نظر پوشش دهید. می توانید پوشرنگ روغنی براق پالاژشیمی را با مذیب مناسب مانند روغن معدنی یا تینر به دلخواه خود رقیق کنید. با استفاده از فرش رنگ، مو، یا رولر رنگ، رنگ را به تدریج روی سطح بمالید. برای ایجاد پوشش مناسب، ممکن است نیاز باشد تا چندین لایه رنگ روی یکدیگر اعمال کنید. بهتر است پوششهای باریک را با

فرش رنگ کوچک و پوششهای پهن را با رولر رنگ اعمال کنید.

سطحی

اساعت





Alkyd paint can be used on all surfaces, including plaster, metal, wooden, etc., and this paint is widely used in the construction industry. . These paints are used to protect all types of structures against various environmental factors, such as high humidity, as well as to prevent rusting of metal structures, etc.



According to the standard (ISO 8504:1992), the

substrate must be free of any contamination

such as fat, oil, dust and moisture, because

these factors cause a severe reduction in the

adhesion of the paint to the surface. Cleaning

should be done with suitable detergents. If the

lining surface is smooth and polished, in order

to create more adhesion, the surface should be

worn with a suitable tool such as sandpaper. If

the paint is applied directly on the surface, the


corresponding preparation must be done on

the desired surface first. Damaged areas of the


surface should also be prepared and painted

again before applying paint.





drying time



quality grade



To use Palajshimi glossy oil paint, first clean the intended surface thoroughly and remove any kind of contamination and grease. Then apply the Palajshimi glossy oil paint on the desired surface using a paintbrush, hairbrush, or roller. You can dilute Palajshimi glossy oil paint with a suitable solvent such as mineral oil or thinner according to your preference. Gradually apply the paint on the surface with a paintbrush, hairbrush, or roller. It may be necessary to apply several layers of paint on top of each other to create a suitable coating. It is preferable to use small paintbrushes for narrow surfaces and rollers for wider surfaces.




Method of Use



سازمان ملی استناندارد ایران Palaj

packing 2/5 Gallon Gallon Quart

Implementation tools



Brush roller pistol Airless

Consumption



One liter

5 square meters

Attributes




Excellent adhesion Special and standard fam Excellent coverage Smooth and polished surface Moisture resistant Resistance to weather conditions



Semi Glossy alkyd oil paint

Surface temperature



degrees Celsius

Expiration date

months

Solvent type



safety

- It is recommended to avoid continuous inhalation of solvent vapors of this color in closed spaces and use appropriate safety equipment as much as possible and wash with plenty of water in case of contact with skin and eyes.
- This paint is flammable and should be kept away from heat, sparks and flames.